

| Roadway Name | Curbs | Sidewalks | Length | Width | Sq. Feet | Sq. Yds | Age | Drainage | Rating | Alligator | Longitudinal | Transverse | Rutting | Patching | General Comments | Date Inspected |
|--|-------|-----------|--------|-------|----------|---------|-------------|-----------|-----------|-----------|--------------|------------|---------|----------|--|----------------|
| 2ND ST | No | No | 685 | 20 | 13700 | 1522.2 | 16+ Years | Poor | Poor | High | Low | Low | Medium | High | Widening, re-routing, and Full Depth Reclamation (FDR) | 11/16/2017 |
| ARBOR ROSE AVE | Yes | Yes | 2024 | 34 | 68816 | 7646.2 | 16+ Years | Excellent | Excellent | None | Low | None | None | None | Crack seal and Micro-surfacing | 11/16/2017 |
| BAILEY LN | Yes | Yes | 811 | 34 | 27574 | 3063.8 | 3-5 Years | Excellent | Excellent | None | None | None | None | None | Micro-surface | 11/21/2017 |
| BERNHARD AVE | Yes | No | 641 | 31 | 19871 | 2207.9 | 16+ Years | Good | Poor | High | Medium | Medium | Low | Low | Scratch, fabric, and overlay | 11/16/2017 |
| BIRCHLAND AVE | No | No | 1763 | 22 | 38786 | 4309.6 | 16+ Years | Poor | Poor | Medium | High | High | Low | Medium | Widen, overlay, and drainage | 11/21/2017 |
| BLOSSOM TRL | Yes | Yes | 1547 | 34 | 52598 | 5844.2 | 16+ Years | Good | Good | None | Medium | Low | None | None | Crack seal and Micro-surfacing | 11/16/2017 |
| BRIDGE BLVD | Yes | Yes | 667 | 33 | 22011 | 2445.7 | 0-2 Years | Excellent | Excellent | None | None | None | None | None | Micro-surface | 11/21/2017 |
| BRUCE AVE | No | No | 1585 | 18 | 28530 | 3170.0 | 0-2 Years | Poor | Good | None | None | None | High | None | Overlay 3-5 years, reconstruction in future | 11/21/2017 |
| CEDAR LN | No | No | 515 | 19 | 9785 | 1087.2 | 11-15 Years | Good | Fair | Low | Medium | Low | None | Low | Crack seal immediately and overlay | 11/16/2017 |
| CHARLAN BLVD | Yes | Yes | 1309 | 34 | 44506 | 4945.1 | 3-5 Years | Excellent | Excellent | None | None | None | None | None | Micro-surface | 11/21/2017 |
| CHARTER LN | Yes | Yes | 1137 | 30 | 34110 | 3790.0 | 16+ Years | Poor | Poor | High | High | High | High | Medium | Reconstruction needed as well as drainage | 11/30/2017 |
| CHESTNUT ST | No | No | 211 | 24 | 5064 | 562.7 | 16+ Years | Good | Good | Low | None | None | None | High | Crack seal | 12/7/2017 |
| CHOCOLATE AVE | Yes | Yes | 747 | 34 | 25398 | 2822.0 | 16+ Years | Good | Poor | High | Medium | Medium | Low | High | Mill, fabric, and overlay | 11/30/2017 |
| CHURCH ST (from Keinath to N Plum) | Yes | Yes | 625 | 34 | 21250 | 2361.1 | 16+ Years | Good | Good | None | Low | Low | None | Medium | Crack seal and micro surfacing | 12/6/2017 |
| CHURCH ST (from N Angle to Orchard) | Yes | Partial | 1314 | 34 | 44676 | 4964.0 | 16+ Years | Good | Poor | Medium | Medium | Medium | None | Medium | Crack seal, micro surfacing | 12/6/2017 |
| CHURCH ST (from N Plum to N Angle) | Yes | Yes | 924 | 34 | 31416 | 3490.7 | 16+ Years | Good | Good | None | Low | Low | None | Medium | Crack seal and micro surfacing | 12/6/2017 |
| COLONY LN | Yes | Partial | 445 | 30 | 13350 | 1483.3 | 16+ Years | Good | Fair | High | Low | Medium | None | Low | Mill, fabric, overlay | 11/30/2017 |
| COLUMBIA AVE (from Pinkerton to S Market) | Yes | Yes | 850 | 34 | 28900 | 3211.1 | 16+ Years | Good | Good | Low | Medium | None | None | Low | Seal coat/micro surface | 11/30/2017 |
| COLUMBIA AVE (from S Market to S Barbara) | Yes | Yes | 1296 | 34 | 44064 | 4896.0 | 16+ Years | Fair | Poor | High | Medium | Low | Low | Low | Mill, fabric, overlay, and drainage | 11/30/2017 |
| CONCORD ST | Yes | No | 763 | 25 | 19075 | 2119.4 | 16+ Years | Good | Poor | High | Medium | Medium | Low | Medium | Mill fabric overlay | 12/1/2017 |
| CORNERSTONE DR | Yes | Yes | 1200 | 34 | 40800 | 4533.3 | 6-10 Years | Good | Fair | None | High | Low | None | Low | Micro surfacing /seal coat, Crack sealing | 12/1/2017 |
| CREEKSIDE LN | Yes | No | 774 | 30 | 23220 | 2580.0 | 11-15 Years | Good | Poor | Medium | High | Medium | None | Medium | Mill fabric overlay Crack seal | 12/1/2017 |
| DAVID ST (from New Haven to W Donegal) | Yes | Partial | 971 | 21 | 20391 | 2265.7 | 11-15 Years | Good | Poor | High | Medium | Medium | None | Medium | Mill overlay fabric, treat like an alley from lumber to church | 12/1/2017 |
| DAVID ST (from S Comfort Alley to New Haven) | Yes | No | 604 | 21 | 12684 | 1409.3 | 6-10 Years | Good | Excellent | None | None | None | None | None | Micro surfacing or seal coat | 12/1/2017 |
| DELTA ST (from Marietta Ave to Cul-De-Sac) | No | Partial | 1768 | 34 | 60112 | 6679.1 | 11-15 Years | Fair | Good | Low | Low | Low | None | Low | Seal coat/micro surfacing | 11/30/2017 |
| DETWILER AVE | Yes | Yes | 1221 | 25 | 30525 | 3391.7 | 16+ Years | Fair | Poor | Low | High | Medium | None | High | Mill, fabric, and overlay Crack seal | 12/6/2017 |
| E DONEGAL ST (from Marietta to Market) | Yes | Yes | 178 | 30 | 5340 | 593.3 | 11-15 Years | Good | Good | None | Medium | None | None | None | Crack seal & Microsurface | 1/10/2018 |
| E DONEGAL ST (from Longenecker to Barbara) | Yes | Partial | 1903 | 34 | 64702 | 7189.1 | 16+ Years | Good | Good | None | Medium | Low | None | Low | Base repair, Crack seal, micro surfacing | 12/6/2017 |

| Roadway Name | Curbs | Sidewalks | Length | Width | Sq. Feet | Sq. Yds | Age | Drainage | Rating | Alligator | Longitudal | Transverse | Rutting | Patching | General Comments | Date Inspected |
|---|-------|-----------|--------|-------|----------|---------|------------|-----------|-----------|-----------|------------|------------|---------|----------|--|----------------|
| E HENRY ST | No | No | 628 | 18 | 11304 | 1256.0 | 16+ Years | Fair | Poor | High | High | High | High | High | Train station reconstruction project | 12/6/2017 |
| EBY CHIQUES RD | No | No | 1213 | 24 | 29112 | 3234.7 | 16+ Years | Good | Good | None | Low | None | Low | None | Suggest widening, crack seal | 12/6/2017 |
| ELLA DR | Yes | Yes | 256 | 34 | 8704 | 967.1 | 3-5 Years | Excellent | Excellent | None | None | None | None | None | Crack seal and micro surfacing | 12/6/2017 |
| FARMINGTON WAY | Yes | Partial | 1503 | 34 | 51102 | 5678.0 | 3-5 Years | Excellent | Excellent | None | None | None | None | None | Crack seal and micro surfacing | 12/6/2017 |
| FARMVIEW LN | Yes | Partial | 1461 | 34 | 49674 | 5519.3 | 16+ Years | Good | Poor | High | High | High | Low | High | FDR | 12/6/2017 |
| FLORIN AVE (from dead end to DSR) | Yes | No | 428 | 31 | 13268 | 1474.2 | 16+ Years | Fair | Poor | Medium | Medium | Medium | Low | Medium | Crack seal and micro surfacing, possible mill fabric overlay | 12/6/2017 |
| FLORIN AVE (from DSR to School Ln) | Yes | Yes | 998 | 30 | 29940 | 3326.7 | 3-5 Years | Good | Excellent | None | None | None | None | Low | Crack seal and micro surfacing | 12/6/2017 |
| FLORIN AVE (from School Ln to Borough Line) | Yes | Yes | 1629 | 34 | 55386 | 6154.0 | 16+ Years | Good | Good | High | Low | None | None | None | Crack seal and micro surfacing | 12/6/2017 |
| FRANK ST | Yes | Partial | 1134 | 26 | 29484 | 3276.0 | 16+ Years | Good | Good | None | Low | None | None | Medium | Crack seal and micro surfacing | 12/6/2017 |
| FREDERICK ST | No | No | 314 | 21 | 6594 | 732.7 | 16+ Years | Good | Good | None | Low | Low | None | Low | Crack seal | 12/6/2017 |
| GLENN AVE (from DSR to Martin Ave) | Yes | Yes | 300 | 30 | 9000 | 1000.0 | 16+ Years | Fair | Poor | Medium | High | High | Low | Medium | FDR along w/ Martin Ave | 12/6/2017 |
| GLENN AVE (from Florin to Blossom Trail) | Yes | Yes | 1110 | 30 | 33300 | 3700.0 | 16+ Years | Good | Poor | Low | Medium | Medium | Low | Medium | Mill, fabric, overlay, micro surfacing, Crack seal | 12/6/2017 |
| GRANDVIEW CIR | Yes | No | 313 | 34 | 10642 | 1182.4 | 16+ Years | Excellent | Good | Low | Low | None | None | None | Crack seal and micro surfacing | 12/7/2017 |
| HEMP ST | No | No | 222 | 12 | 2664 | 296.0 | 16+ Years | Poor | Poor | Medium | High | Medium | Low | High | Mill overlay fabric | 12/7/2017 |
| HILL ST (from N Angle to Orchard) | Yes | Partial | 986 | 18 | 17748 | 1972.0 | 6-10 Years | Excellent | Excellent | None | Low | None | None | None | Crack seal and micro surfacing | 12/7/2017 |
| HILL ST (from N Plum to N Angle) | Yes | Partial | 935 | 18 | 16830 | 1870.0 | 6-10 Years | Excellent | Excellent | None | Low | None | None | None | Crack seal and micro surfacing | 12/7/2017 |
| HOPEWELL ST (from 772 to Fairview) | No | No | 418 | 17 | 7106 | 789.6 | 16+ Years | Fair | Poor | High | Medium | Medium | Low | High | Mill overlay fabric | 12/7/2017 |
| HOPEWELL ST (from Old Stand By to Fairview) | No | No | 279 | 17 | 4743 | 527.0 | 6-10 Years | Good | Excellent | None | None | None | None | None | Crack seal | 12/7/2017 |
| ICE ST | No | No | 219 | 24 | 5256 | 584.0 | 6-10 Years | Excellent | Excellent | None | None | None | None | Low | Crack seal | 12/7/2017 |
| JASMINE AVE | Yes | Yes | 208 | 33 | 6864 | 762.7 | 3-5 Years | Excellent | Excellent | None | None | None | None | None | Crack seal and micro surfacing | 12/6/2017 |
| JOY AVE | No | No | 264 | 22 | 5808 | 645.3 | 16+ Years | Good | Fair | Low | Low | None | None | High | Crack seal and micro surfacing | 12/6/2017 |
| LAUVER DR | No | No | 328 | 12 | 3936 | 437.3 | 3-5 Years | Excellent | Excellent | None | None | None | None | None | Crack seal | 12/13/2017 |
| LEMON ST | No | No | 239 | 15 | 3585 | 398.3 | 16+ Years | Good | Fair | Medium | Medium | Low | None | Medium | Reconstruction planned | 12/7/2017 |
| LIBERTY CT | Yes | Yes | 423 | 30 | 12690 | 1410.0 | 16+ Years | Good | Fair | High | Medium | Low | None | Low | Mill fabric overlay | 12/13/2017 |
| LOCUST LN | Yes | Partial | 1854 | 34 | 63036 | 7004.0 | 16+ Years | Fair | Poor | High | High | Medium | None | High | Reconstruction and take core samples | 12/13/2017 |
| LUMBER ST (from 772 to dead end) | Yes | Partial | 1238 | 20 | 24760 | 2751.1 | 16+ Years | Good | Poor | High | High | Medium | Low | Low | Mill fabric and overlay | 12/13/2017 |
| LUMBER ST (from W Main to W Henry) | Yes | Yes | 275 | 20 | 5500 | 611.1 | 16+ Years | Good | Fair | Medium | Medium | Low | None | None | FDR | 12/13/2017 |
| MARTIN AVE (from dead end to Florin) | Yes | Yes | 630 | 30 | 18900 | 2100.0 | 16+ Years | Good | Fair | Medium | Medium | Low | None | Low | Reconstruction | 12/13/2017 |

| Roadway Name | Curbs | Sidewalks | Length | Width | Sq. Feet | Sq. Yds | Age | Drainage | Rating | Alligator | Longitudal | Transverse | Rutting | Patching | General Comments | Date Inspected |
|---|-------|-----------|--------|-------|----------|---------|-------------|-----------|-----------|-----------|------------|------------|---------|----------|---|----------------|
| MARTIN AVE (from Florin to Farmview) | Yes | Yes | 1580 | 34 | 53720 | 5968.9 | 16+ Years | Good | Fair | Medium | Medium | Low | None | Medium | Micro surfacing and reconstruction | 12/13/2017 |
| MIDWAY RD | Yes | Partial | 869 | 34 | 29546 | 3282.9 | 16+ Years | Fair | Poor | High | High | Medium | None | Low | Reconstruction | 12/13/2017 |
| MOUNT JOY ST | Yes | Yes | 1444 | 33 | 47652 | 5294.7 | 16+ Years | Good | Poor | Medium | Medium | Medium | Low | High | Mill overlay fabric | 12/7/2017 |
| N ANGLE ST (from Bruce to Terrace) | No | No | 494 | 19 | 9386 | 1042.9 | 16+ Years | Good | Poor | High | High | Medium | Low | High | Reconstruction | 12/13/2017 |
| N ANGLE ST (from Hill to Main) | No | Partial | 1687 | 26 | 43862 | 4873.6 | 16+ Years | Good | Poor | High | High | Medium | Medium | High | Reconstruction | 12/13/2017 |
| N ANGLE ST (from Terrace to Hill) | No | No | 833 | 36 | 29988 | 3332.0 | 16+ Years | Good | Poor | High | High | Medium | Medium | High | Reconstruction | 12/13/2017 |
| N BARBARA ST (from 772 to Detwiler) | Yes | Partial | 1236 | 28 | 34608 | 3845.3 | 16+ Years | Good | Poor | Medium | Medium | Low | Low | High | Mill overlay fabric | 12/7/2017 |
| N BARBARA ST (from Detwiler to E Main) | Yes | Yes | 1232 | 28 | 34496 | 3832.9 | 16+ Years | Good | Poor | Medium | Low | Low | Low | High | Mill overlay fabric | 12/7/2017 |
| N HIGH ST | No | Partial | 1413 | 32 | 45216 | 5024.0 | 16+ Years | Good | Fair | Low | Medium | None | None | High | Crack seal and Microsurface | 12/7/2017 |
| N JACOB ST | Yes | Partial | 636 | 25 | 15900 | 1766.7 | 16+ Years | Fair | Poor | Medium | Medium | Low | None | High | Overlay Crack seal | 12/18/2017 |
| N MARKET AVE | Yes | Partial | 1195 | 36 | 43020 | 4780.0 | 16+ Years | Good | Fair | Low | High | Low | None | Low | Crack sealing, Overlay | 12/18/2017 |
| N MARKET ST | Yes | Yes | 3064 | 33 | 101112 | 11234.7 | 6-10 Years | Excellent | Good | None | Low | None | None | Low | Crack seal and Microsurface | 12/18/2017 |
| N PLUM ST (from Pleasure to Borough Line) | No | No | 1258 | 18 | 22644 | 2516.0 | 16+ Years | Poor | Poor | High | High | High | Medium | Medium | Reconstruction | 12/18/2017 |
| N PLUM ST (from W Main to Pleasure Rd) | Yes | Partial | 1719 | 29 | 49851 | 5539.0 | 16+ Years | Poor | Poor | High | High | Low | Low | High | Reconstruction | 12/18/2017 |
| NEW HAVEN ST (from 772 to Oak Aly) | Yes | No | 214 | 34 | 7276 | 808.4 | 16+ Years | Good | Good | Medium | Low | Low | None | None | Base repair | 12/18/2017 |
| NEW HAVEN ST (from W Donegal to 772) | Yes | Yes | 885 | 34 | 30090 | 3343.3 | 16+ Years | Good | Poor | High | High | High | Medium | High | Reconstruction | 12/18/2017 |
| NEW ST (from S Barbara to S Jacob) | No | No | 895 | 28 | 25060 | 2784.4 | 16+ Years | Poor | Poor | High | Medium | High | None | Low | Reconstruction & widening | 12/18/2017 |
| NEW ST (from Walnut to S Barbara) | Yes | Partial | 410 | 28 | 11480 | 1275.6 | 11-15 Years | Good | Good | Low | Low | None | None | None | Crack Seal and Microsurface | 12/18/2017 |
| NEWCOMER RD | Yes | Partial | 473 | 19 | 8987 | 998.6 | 0-2 Years | Excellent | Excellent | None | None | None | None | None | Crack seal when needed and Microsurface | 12/18/2017 |
| OLD MARKET ST (from 772 to Borough Line) | No | Partial | 480 | 32 | 15360 | 1706.7 | 0-2 Years | Excellent | Excellent | None | None | None | None | None | Crack Seal and Microsurface | 12/18/2017 |
| OLD MARKET ST (from N Market to 772) | Yes | Yes | 845 | 25 | 21125 | 2347.2 | 16+ Years | Good | Fair | Low | Medium | None | None | Medium | Crack seal & micro surfacing | 12/18/2017 |
| ORANGE ST | No | No | 617 | 17 | 10489 | 1165.4 | 16+ Years | Poor | Fair | High | Low | Low | Low | Low | Reconstruction & widening | 12/18/2017 |
| ORCHARD RD (from Bruce to Hill) | No | No | 1075 | 20 | 21500 | 2388.9 | 16+ Years | Poor | Poor | High | Medium | Low | None | High | Reconstruction & widening | 12/18/2017 |
| ORCHARD RD (from Hill to W Main) | Yes | Yes | 1384 | 36 | 49824 | 5536.0 | 11-15 Years | Good | Good | None | Medium | None | None | None | Crack sealing micro surfacing | 12/18/2017 |
| PARK AVE | No | No | 2633 | 21 | 55293 | 6143.7 | 6-10 Years | Fair | Fair | Low | Low | None | Low | Medium | FDR | 12/27/2017 |
| PEACE AVE | Yes | Yes | 636 | 34 | 21624 | 2402.7 | 11-15 Years | Good | Excellent | None | None | None | None | None | Crack seal and micro surfacing | 12/28/2017 |
| PINE ST | No | No | 625 | 21 | 13125 | 1458.3 | 16+ Years | Fair | Fair | Medium | Low | Low | None | High | Micro surfacing | 12/28/2017 |
| PINKERTON RD | No | No | 1820 | 18 | 32760 | 3640.0 | 16+ Years | Poor | Poor | High | High | High | Medium | High | FDR | 12/28/2017 |

| Roadway Name | Curbs | Sidewalks | Length | Width | Sq. Feet | Sq. Yds | Age | Drainage | Rating | Alligator | Longitudal | Transverse | Rutting | Patching | General Comments | Date Inspected |
|---|-------|-----------|--------|-------|----------|---------|-------------|-----------|-----------|-----------|------------|------------|---------|----------|--|----------------|
| POPLAR ST | Yes | Yes | 889 | 34 | 30226 | 3358.4 | 16+ Years | Good | Good | None | Low | None | None | Low | Crack seal & micro surfacing | 12/27/2017 |
| RICHLAND LN | No | No | 1314 | 25 | 32850 | 3650.0 | 16+ Years | Fair | Poor | Medium | Medium | High | Medium | Low | FDR | 12/27/2017 |
| ROSE PETAL LN | Yes | Yes | 1782 | 34 | 60588 | 6732.0 | 11-15 Years | Good | Excellent | None | Low | None | None | None | Crack seal and Microsurface | 12/28/2017 |
| S BARBARA ST | Yes | Yes | 1304 | 34 | 44336 | 4926.2 | 11-15 Years | Good | Good | Low | Low | Low | None | Low | Micro surfacing and Crack seal | 12/27/2017 |
| S HIGH ST (from E Donegal to South Aly) | Yes | Yes | 214 | 29 | 6206 | 689.6 | 11-15 Years | Fair | Fair | High | Low | Low | None | None | Mill overlay | 12/27/2017 |
| S HIGH ST (from E Main to Sassafras Aly) | Yes | Partial | 223 | 33 | 7359 | 817.7 | 16+ Years | Fair | Poor | High | Medium | Medium | Low | Medium | Mill and overlay | 12/27/2017 |
| S JACOB ST (from dead end to Borough Line) | Yes | Partial | 1418 | 37 | 52466 | 5829.6 | 16+ Years | Poor | Poor | High | High | High | High | High | FDR | 12/27/2017 |
| S JACOB ST (from E Main to Sassafras Aly) | Yes | Yes | 222 | 37 | 8214 | 912.7 | 16+ Years | Good | Good | Low | Low | None | None | Low | Mill and overlay | 12/28/2017 |
| S MARKET AVE (from dead end to Wood) | Yes | Yes | 262 | 20 | 5240 | 582.2 | 3-5 Years | Excellent | Excellent | None | None | None | None | None | Crack Seal | 12/28/2017 |
| S MARKET AVE (from W Main to dead end) | Yes | Yes | 589 | 34 | 20026 | 2225.1 | 11-15 Years | Excellent | Excellent | None | None | None | None | None | Crack sealing | 12/27/2017 |
| S MARKET AVE (from Wood to DSR) | Yes | Partial | 1617 | 20 | 32340 | 3593.3 | 16+ Years | Fair | Poor | Medium | Medium | Medium | Medium | High | FDR | 12/28/2017 |
| S MARKET ST (from 230 to 772) | Yes | Yes | 660 | 36 | 23760 | 2640.0 | 16+ Years | Good | Good | Low | Medium | None | Low | None | Mill overlay | 12/27/2017 |
| S MARKET ST (from 772 to dead end) | Yes | Partial | 1483 | 36 | 53388 | 5932.0 | 6-10 Years | Good | Excellent | None | Low | None | None | None | Crack seal and Microsurface | 12/27/2017 |
| S MELHORN DR | Yes | No | 305 | 33 | 10065 | 1118.3 | 11-15 Years | Excellent | Good | None | Low | None | None | Low | Crack Seal | 12/28/2017 |
| S PLUM ST (from dead end to Wood) | Yes | Partial | 238 | 32 | 7616 | 846.2 | 16+ Years | Fair | Fair | Low | Low | Low | Low | Low | Mill and overlay | 12/28/2017 |
| S PLUM ST (from Wood to DSR) | Yes | Yes | 1906 | 32 | 60992 | 6776.9 | 0-2 Years | Excellent | Excellent | None | None | None | None | None | Crack Seal & micro surfacing | 12/28/2017 |
| S PLUMB ST (from W Main to Square St) | No | Partial | 693 | 22 | 15246 | 1694.0 | 16+ Years | Fair | Poor | Low | Medium | None | Medium | High | FDR | 12/27/2017 |
| SCHOOL LN (from 772 to Pinkerton) | Yes | No | 1630 | 32 | 52160 | 5795.6 | 16+ Years | Good | Poor | High | High | High | Low | High | FDR | 12/27/2017 |
| SCHOOL LN (from Blossom Trail to 772) | Yes | Partial | 1247 | 40 | 49880 | 5542.2 | 11-15 Years | Good | Good | Medium | Low | None | None | Low | Base repair & micro surfacing & Crack seal | 12/27/2017 |
| SCHOOL LN (from dead end to Blossom Trail) | Yes | No | 1258 | 40 | 50320 | 5591.1 | 11-15 Years | Good | Excellent | None | Low | None | None | None | Crack seal and Microsurface | 12/27/2017 |
| SCHOOL LN (from Pinkerton to S Market) | Yes | No | 1027 | 22 | 22594 | 2510.4 | 16+ Years | Poor | Poor | High | Medium | High | Medium | High | FDR | 12/27/2017 |
| SCHOOL LN (from S Market to dead end) | No | No | 509 | 22 | 11198 | 1244.2 | 16+ Years | Poor | Poor | High | High | High | Medium | High | FDR | 12/27/2017 |
| SELLER LN | No | No | 427 | 15 | 6405 | 711.7 | 3-5 Years | Good | Excellent | None | Low | None | None | None | Crack seal | 12/28/2017 |
| SPRINGVILLE RD | No | No | 998 | 20 | 19960 | 2217.8 | 16+ Years | Fair | Poor | High | Medium | High | None | Medium | Mill and overlay | 12/28/2017 |
| SQUARE ST (from dead end to S Angle bridge) | No | Partial | 1397 | 18 | 25146 | 2794.0 | 16+ Years | Fair | Poor | High | Low | Low | High | Low | FDR | 12/27/2017 |
| SQUARE ST (from S Angle bridge to Orange) | No | No | 725 | 18 | 13050 | 1450.0 | 16+ Years | Good | Fair | Low | Low | Low | Low | High | Crack sealing and Microsurface | 12/27/2017 |
| STAUFER CT | Yes | No | 583 | 30 | 17490 | 1943.3 | 16+ Years | Good | Poor | High | Medium | Medium | None | High | FDR | 1/10/2018 |
| SUNSET AVE | Yes | Yes | 474 | 30 | 14220 | 1580.0 | 16+ Years | Good | Poor | High | High | Medium | None | High | FDR | 1/10/2018 |

| Roadway Name | Curbs | Sidewalks | Length | Width | Sq. Feet | Sq. Yds | Age | Drainage | Rating | Alligator | Longitudal | Transverse | Rutting | Patching | General Comments | Date Inspected |
|---|-------|-----------|--------|-------|----------|---------|------------|-----------|-----------|-----------|------------|------------|---------|----------|---------------------------------|----------------|
| TAYLOR AVE | Yes | Yes | 535 | 34 | 18190 | 2021.1 | 0-2 Years | Excellent | Excellent | None | None | None | None | None | Crack seal and Microsurface | 1/10/2018 |
| TERRACE AVE | Yes | No | 1660 | 29 | 48140 | 5348.9 | 16+ Years | Fair | Poor | High | Medium | Medium | None | Low | FDR | 1/10/2018 |
| W DONEGAL ST (from both sides of DSR) | Yes | Partial | 906 | 30 | 27180 | 3020.0 | 16+ Years | Fair | Poor | High | Medium | Low | Low | High | Drainage, FDR | 1/10/2018 |
| W DONEGAL ST (from New Haven to Market) | Yes | Yes | 1038 | 30 | 31140 | 3460.0 | 6-10 Years | Excellent | Good | None | Low | None | None | Low | Crack Seal & Microsurface | 1/10/2018 |
| W HENRY ST (from dead end to New Haven) | No | No | 933 | 18 | 16794 | 1866.0 | 0-2 Years | Excellent | Excellent | None | None | None | None | None | Crack Seal | 1/10/2018 |
| W HENRY ST (from New Haven to S Market) | No | No | 1035 | 18 | 18630 | 2070.0 | 16+ Years | Poor | Poor | High | High | High | Low | High | Current train station project | 1/10/2018 |
| WALNUT ST | No | No | 660 | 19 | 12540 | 1393.3 | 16+ Years | Poor | Poor | High | High | Medium | None | Medium | FDR | 1/10/2018 |
| WATER ST (from Alden to N Plum) | No | Partial | 1088 | 24 | 26112 | 2901.3 | 3-5 Years | Good | Good | None | Medium | None | None | None | Crack seal and Microsurface | 1/10/2018 |
| WATER ST (from N Angle to dead end) | No | No | 275 | 18 | 4950 | 550.0 | 6-10 Years | Fair | Poor | High | Medium | Medium | None | Low | FDR | 1/10/2018 |
| WATER ST (from N Plum to N Angle) | No | Partial | 932 | 18 | 16776 | 1864.0 | 16+ Years | Fair | Poor | Medium | Medium | Low | Low | Medium | FDR and widen | 1/10/2018 |
| WOOD ST (from Chocolate to Florin) | No | No | 944 | 10 | 9440 | 1048.9 | 16+ Years | Poor | Poor | High | High | Low | Low | Low | FDR | 1/10/2018 |
| WOOD ST (from Musser to S Plum) | Yes | Partial | 2039 | 34 | 69326 | 7702.9 | 6-10 Years | Fair | Fair | Medium | Medium | Low | None | Low | FDR | 1/10/2018 |
| WOOD ST (from S Plum to Chocolate) | Yes | Partial | 1817 | 34 | 61778 | 6864.2 | 16+ Years | Poor | Poor | High | High | Medium | None | High | FDR | 1/10/2018 |
| ZIEGLER ST | No | No | 381 | 30 | 11430 | 1270.0 | 16+ Years | Good | Fair | Medium | Low | Low | None | Medium | Crack seal. Mill fabric overlay | 1/10/2018 |